

Change in Backlashes of SSAY Spur Gears with Built-in Clamps

Product	Backlash (with the same No. of teeth)		
	Before Change	Changed	
SSAY0.8-28/K6	0.10 to 0.20	0 to 0.10	
SSAY0.8-30/K6			
SSAY0.8-30/K8			
SSAY0.8-32/K6			
SSAY0.8-32/K8			
SSAY0.8-35/K6			
SSAY0.8-35/K8			
SSAY0.8-36/K6			
SSAY0.8-36/K8			
SSAY0.8-40/K6			
SSAY0.8-40/K8			
SSAY0.8-40/K10			
SSAY0.8-45/K6			0.12 to 0.24
SSAY0.8-45/K8			
SSAY0.8-45/K10			
SSAY0.8-48/K6			
SSAY0.8-48/K8			
SSAY0.8-48/K10			
SSAY0.8-50/K6			
SSAY0.8-50/K8			
SSAY0.8-50/K10			
SSAY0.8-55/K6			
SSAY0.8-55/K8			
SSAY0.8-55/K10			
SSAY0.8-56/K6			
SSAY0.8-56/K8			
SSAY0.8-56/K10			
SSAY0.8-60/K6			
SSAY0.8-60/K8			
SSAY0.8-60/K10			