

Change in Backlash of SSY/BSS Spur Gears

Product		Backlash (with the same No. of teeth)	
Series	Catalog No.	Before Change	Changed
SSY	SSY0.8-20	0.06 to 0.16	0 to 0.10
	SSY0.8-25	0.10 to 0.20	
	SSY0.8-30		
	SSY0.8-40		
	SSY0.8-50	0.12 to 0.24	
BSS	BSS0.5-20	0.06 to 0.16	0 to 0.10
	BSS0.5-25	0.10 to 0.20	
	BSS0.5-30		
	BSS0.5-40		
	BSS0.8-20	0.06 to 0.16	
	BSS0.8-25	0.10 to 0.20	
	BSS0.8-30		
	BSS0.8-40		